

## **POWER VENTILATORS INSTALLATION/TROUBLESHOOTING**

- THE MAIN CAUSE OF POWER VENTILATOR MOTOR FAILURES IS INADEQUATE INTAKE.
- THE LOMANCOOL 2000 IS EQUIPPED WITH A RAINSHIELD. IT, AS WELL AS THE BASE, IS STAMPED WITH "UP" TO INDICATE THE SIDE THAT SHOULD BE FACING THE PEAK OF THE ROOF.
- A PIGTAIL CONNECTION SHOULD BE USED TO CHECK WARRANTY MOTORS PRIOR TO RETURNING TO THE FACTORY.
- CARE SHOULD BE EXERCISED DURING INSTALLATION SO THAT THE MOTOR SUPPORTS DO NOT TOUCH THE DECKING OR TRUSSES.